

1

2

3

4

5

## Einzelverdrahtung

Drahtsorte FSL 0,5 WN 5733

A

1 gert Z2c - y3

2 rt Z4c - v5

3 geb1 Z5c - n4

4 wsbl Z6c - y5

B

5 blrt Y1a - b36

6 gr Y2a - b37

7 ws Y3a - b38

8 sw Y4a - b39

9 br Y5a - b40

10 rs Y6a - b41

C

11 rtsw Y0a - b14

12 gn Y1b - b4

13 rtsw Y2b - b5

14 blrt Y3b - b6

15 gr Y4b - b8

16 ws Y5b - b9

17 sw Y6b - b11

18 rs Y8b - b13

19 brge Y9b - b12

20 ge Y0b - b3

21 br Z1a - b15

22 rs Z2a - b16

23 brge Z3a - b17

E

24 ge Z4a - b19

25 gn Z5a - b20

26 rtsw Z6a - b21

27 blrt Z7a - b22

28 gr Z8a - b23

29 ws Z9a - b25

F

30 sw Z0a - b26

31 ws Z1b - b27

32 sw Z2b - b28

33 br Z3b - b29

34 rs Z4b - b31

35 brge Z5b - b32

36 ge Z6b - b33

37 gn Z7b - b34

38 rtsw Z8b - b35

39 ws Z7c - y2

40 sw Z8c - y9

41 br Z9c - y22

42 rs Z0c - y29

43 wsgn h6 - 16

44 wsgn h9 - k7

45 wsgn h16 - 118

46 wsgn h19 - k18

47 wsgn h22 - k19

48 wsgn 120 - 128

49 wsgn h25 - 127

50 wsgn h28 - k28

51 wsgn h32 - 133

52 wsgn h35 - k34

53 wsgn 135 - p40

54 wsgn h37 - 137

55 wsgn h39 - k38

56 wsge g13 - o19

57 wsge g14 - p17

58 wsge g40 - o40

59 wsge g41 - p41

60 wsge f10 - k33

3

73-542

Freimaßtoleranzen

Maßstab

ZÄS 1-01

Zählersteuerung

Gez.

Blatt

STANDARD  
ELEKTRIK  
LORENZ

3861 - 1366 - 1

a	30.11.59	NIF 789	d Müller	Ma
Ausg.	Tag	Mitteilung	Bearbeiter	Geprüft
				Normg. Bes.